# Weekly meeting

SNU

BongHo Kim

Issue at the P-bar line meeting

- P-bar trap length issue with gate valve (page3)

- Ion pump place at downstream of pbar trap (need to adjust iron shield)

- Rack position of pbar trap (page4)

- BPM (beam profile monitor) at upstream : 2-stage MCP (?) + faraday cup

- Installation of steering plates (upstream of the trap)

Antiproton line with trap
Lenses

From JeanYves

Pbar trap rack positions

rail

Rack position 1

Rack spare position

Half rack in reaction chamber racks

TOF issue

- The reason of better time resolution compared with others (need to investigate)

- Inverse interpolation (Bessel function) : less fluctuation than others (linear interpolation)