

<Procedure to fit the top

- 1) Insert the blow out tube in main lead connector.
- 2) Insert the end of the helium plate such as this figure.
- 3) Pull out the blow out tube
- 4) Insert the guide tube of the



LHe probe

Opening for
LHe Probe




Figure 5-7 Proc

