


Trap & Magnet


20200318

박관형

PXI-cRIO connection error



PXI-cRIO connection error




- The connection goes 'disconnected' by time to time.
- Consider changing to Ethernet connection (contact with KU facility team)

Magnet Warm up

- Remove the screws on the Drop-off valve
- Do nothing and Seal the nitrogen opening





전문연 해외출장

- MoU → 한영공증 (30*5000~25000 원)
- New agreement → 한영공증