

Weekly report

2019/05/06

## 1. Gold absorber production



- Two ways

1. Custom order (company : "Goodfellow")

-> disadvantage : rather poor purity of 99.9% and possible pinhole

2. By hand (99.999% gold piece in IBS) with rolling machine

-> disadvantage : in early hammering process, dust could be curled up



## 2. Designing sample( $^{55}\text{Fe}$ ) holder

- Will be drawn by solid works with proper design

