FADC/TDC module issues (SK, 20160628)

Threshold issue

FADC: 2V/4000 (~0.5 mV) * Threshold setting value(T) ex. T=20 —> 10 mV

TDC: 2V/10/4000 (~0.05 mV) * Threshold setting value(T) ex. T=200 —> 10 mV only for negative signal

Currently trigger is done by FADC —> TDC=0 event (?)

Two peak issue

If signal has sholder or noise two TDC hits can be recorded —> check this with FADC signal and two consecutive TDC hits