


Weekly Meeting

15/11/2019

ByungChan Lee

Light Leak – bar C




Plst002-R	1538.00	V	1000.0	uA	0.00	V	0.0	uA	Off
Plst003-L	1498.00	V	1000.0	uA	1498.00	V	682.2	uA	On
Plst003-R	1498.00	V	1000.0	uA	1498.50	V	682.2	uA	On
Plst004-L	1540.00	V	1000.0	uA	0.00	V	0.2	uA	Off
Plst004-R	1555.00	V	1000.0	uA	0.00	V	0.0	uA	Off
CHANNEL08	0.00	V	200.0	uA	0.00	V	0.0	uA	Off
CHANNEL09	0.00	V	200.0	uA	0.00	V	0.0	uA	Off


Tape fell off the bakelite

- Too many stress on tape / Slide of the scintillation bar

New structure



New structure



ORQ gain calibration

